

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

HASNA- P. A.  
Rajagiri Seashore CMI School  
Ernakulam, Vypin  
Permanent Multistoried New  
Building (Details in Over leaf)

5. Period for which the certificate is issued

2025-26

6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

Nil

7. Any major defects noticed which will render the building unsafe in any manner

8. Whether maintenance works have been done properly

Yes

9. Whether the structure is sound or not for conducting classes

Sound under normal weather  
Conditions.


**Note: 1.** The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. **2.** Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

Certified that the school building was inspected by me on 23.05.2025 and found to be fit / unfit to conduct classes, for the period 2025-26 for the reasons stated above.

Place: Malipuram

Date: 23.05.2025



ASSISTANT ENGINEER  
LID & EW SECTION  
ELANKUNNAPUZHA GRAMA PANCHAYAT  
MALIPURAM-682511

**RAJAGIRI SEASHORE CMI SCHOOL, VYPIN**  
**Classification of the buildings - All permanent**

**Year of construction - 2016, Building No. - XIX/469c**

**Ground Floor (Plinth Area 1022.03sq m)**

Sl. No.	Room No.	Nature of the room	Size of rooms with Height (in Meters)	Area (in Sq. Mtr)	Total No. of rooms
1	101	Office /Principal room	7.90 x 7 x 3.50	55.3	1
2	102, 103	Classrooms	5.25x 7 x 3.50	36.75	2
3	1,04,110	Classrooms	7 x 6 x 3.50	42	2
4	105	Classroom	8.60x 5.60 x 3.50	48.16	1
5	106	Kitchen	6.80 x 4.40 x 3.50	29.92	1
6	1,07,108	Classrooms	7 x 6.05 x 3.50	42.35	2
7	109	Computer Lab	9.10 x 7 x3.50	63.7	1
8	111	Counselling room	6 x 3.20 x 3.50	19.2	1
9	112, 113	Sports/Sick rooms	6 x 6 x3.50	36	2
10	114	Toilet block	12.50 x 3.10 x 3.50	38.75	1
<b>Total number of rooms</b>					<b>14</b>

**First Floor (Plinth Area 1098.65sq m)**

Sl. No.	Room No.	Nature of the room	Size of rooms with Height (in Meters)	Area (in Sq. Mtr)	Total No. of rooms
1	201	Maths Lab	10.20 x 5.15 x 3.50	52.53	1
2	202	Library	12.20 x 10.40 x 3.50	126.88	1
3	203 - 209, 211	Classrooms	7 x 6 x 3.50	42	8
4	210	Staff room	7.20 x 7 x 3.50	50.4	1
5	212, 213	Toilet Blocks for boys and girls	7 x 4.25 x3.50	29.75	2
<b>Total number of rooms</b>					<b>13</b>

**Second Floor (Plinth Area 1154.54sq m)**

Sl. No.	Room No.	Nature of the room	Size of rooms with Height (in Meters)	Area (in Sq. Mtr)	Total No. of rooms
1	301	Multipurpose room	10.20 x 5.15 x 3.50	52.53	1
2	302	Composite science lab	12.20 x 10.40 x 3.50	126.88	1
3	303 -309, 311	Classrooms	7 x 6 x 3.50	42	8
4	310	Classroom	7.20 x 7 x 3.50	50.4	1
5	312, 313	Toilet Blocks for boys and girls	7 x 4.25 x3.50	29.75	2
<b>Total number of rooms</b>					<b>13</b>



  
**ASSISTANT ENGINEER**  
**LID & EW SECTION**  
**ELANKUNNAPUZHA GRAMA PANCHAYAT**  
**MALIPURAM-682511**

ASSISTANT ENGINEER  
 LID & EW SECTION  
 ELANKUNNAPUZHA GRAMA PANCHAYAT  
 MALIPURAM-682511